					4	
2	BRS	L2	17183	PLL or DLL	USPA T	2002/09/2 4 16:11
3	BRS	L3	27131 3	lock	USPA T	2002/09/2 4 16:11
4	BRS	L4	6789	2 and 3	USPA T	2002/09/2 4 16:12
5	BRS	L5	6361	"charge pump"	USPA T	2002/09/2 4 16:12
6	BRS	L6	886	4 and 5		2002/09/2 4 17:09
7	BRS	L7	2743	"phase locking"	USPA T	2002/09/2 4 17:10
8	BRS	L8	692	2 and 7		2002/09/2 4 17:10
9	BRS	L9	103	8 and 5	USPA T	2002/09/2 4 17:15
10	BRS .	L10	5695	"frequency synthesizer"		2002/09/2 4 17:19
11	BRS	L11	1636	2 and 10	USPA T	2002/09/2 4 17:19
12	BRS	L12	318	11 and 5		2002/09/2 4 17:19
13	BRS	L13	17	12 and 7	USPA T	2002/09/2 4 17:19
14	BRS	L14		3 and 12		2002/09/2 4 17:20
15	BRS	L15	67479 7	detect\$	÷ .	2002/09/2 4 17:21
16	BRS	L16		switch\$		2002/09/2 4 17:22
17	BRS	L17	30634 2	15 and 16	USPA T	2002/09/2 4 17:24
18	BRS	L18	7285	"impedance state"	USPA T	2002/09/2 4 17:24
19	BRS	L19	30097	"high impedance"	USPA T	2002/09/2 4 17:24
20	BRS	L20	12011	19 and 17	Т	2002/09/2 4 17:25
21	BRS	L21	29	2.0 and 8	Т	2002/09/2 4 17:25
22	BRS	L22	31	20 and 14	USPA. T	2002/09/2 4 17:26

.